

STATE OF TEXAS WELL REPORT for Tracking #585134

Owner: **Kathy Beckham** Owner Well #: **No Data**
Address: **PO Box 280** Grid #: **57-19-5**
Llano, TX 78643
Well Location: **CR 314** Latitude: **30° 40' 41.28" N**
Llano, TX Longitude: **098° 40' 42.24" W**
Well County: **Llano** Elevation: **No Data**
Number of Wells Drilled: **3**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **9/23/2021**

Drilling End Date: **9/23/2021**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	9	0	40
	6.25	40	72

Drilling Method: **Air Hammer; Air Rotary**

Borehole Completion: **Straight Wall**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	-2	3	Cement 1 Bags/Sacks
	3	12	Bentonite 4 Bags/Sacks

Seal Method: **Poured**

Distance to Property Line (ft.): **50+**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **35 ft. below land surface on 2021-09-23**

Measurement Method: **Steel Tape**

Packers: **Rubber at 1 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted**

Yield: 35-40 GPM

Water Quality:	Strata Depth (ft.) 45 - 47	Water Type No Data
----------------	--------------------------------------	------------------------------

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill** License Number: **4168**

Comments: **No Data**

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL			Casing: BLANK PIPE & WELL SCREEN DATA					
Top (ft.)	Bottom (ft.)	Description	Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	1	Topsoil	4.5	Blank	New Plastic (PVC)	40	-2	52
1	40	Red Sandy Clay	4.5	Perforated or Slotted	New Plastic (PVC)	40 0.020	52	72
40	72	Red Granite						

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540

connected to Solar Pump

STATE OF TEXAS WELL REPORT for Tracking #585138

Owner:	Kathy Beckham	Owner Well #:	No Data
Address:	PO Box 280 Llano, TX 78643	Grid #:	57-19-5
Well Location:	CR 314 Llano, TX	Latitude:	30° 40' 36.78" N
Well County:	Llano	Longitude:	098° 40' 39.59" W
Number of Wells Drilled:	4	Elevation:	No Data

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **9/27/2021**

Drilling End Date: **9/27/2021**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	9	0	40
	6.25	40	205

Drilling Method: **Air Hammer; Air Rotary**

Borehole Completion: **Open Hole**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	-2	3	Cement 1 Bags/Sacks
	3	12	Bentonite 4 Bags/Sacks

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **50+**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **38 ft. below land surface on 2021-09-27** Measurement Method: **Steel Tape**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Jettied**

Yield: 6 GPM

	Strata Depth (ft.)	Water Type
Water Quality:	40 - 42	No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill** License Number: **4168**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	1	Topsoil
1	40	Red Sandy Clay
40	205	Red Granite

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
6	Blank	New Plastic (PVC)	40	-2	40

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540

STATE OF TEXAS WELL REPORT for Tracking #585136

Owner: **Kathy Beckham** Owner Well #: **No Data**
Address: **PO Box 280** Grid #: **57-19-5**
Llano, TX 78643
Well Location: **CR 314** Latitude: **30° 40' 38.4" N**
Llano, TX Longitude: **098° 40' 30.71" W**
Well County: **Llano** Elevation: **No Data**
Number of Wells Drilled: **2**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **9/24/2021**

Drilling End Date: **9/24/2021**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	9	0	30
	6.25	30	125

Drilling Method: **Air Hammer; Air Rotary**

Borehole Completion: **Open Hole**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	-2	3	Cement 1 Bags/Sacks
	3	12	Bentonite 4 Bags/Sacks

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **50+**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **38 ft. below land surface on 2021-09-24** Measurement Method: **Steel Tape**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Jetted**

Yield: 15 GPM

	Strata Depth (ft.)	Water Type
Water Quality:	53 - 56	No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill**

License Number: **4168**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	1	Topsoil
1	30	Red Sandy Clay
30	125	Red Granite

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
6	Blank	New Plastic (PVC)	40	-2	32

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540

STATE OF TEXAS WELL REPORT for Tracking #585131

Owner: **Kathy Beckham**

Owner Well #: **No Data**

Address: **PO Box 280
Llano, TX 78643**

Grid #: **57-19-5**

Well Location: **CR 314
Llano, TX**

Latitude: **30° 40' 41.28" N**

Longitude: **098° 40' 42.24" W**

Well County: **Llano**

Elevation: **No Data**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **9/23/2021**

Drilling End Date: **9/23/2021**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	9	0	30
	6.25	30	125

Drilling Method: **Air Hammer; Air Rotary**

Borehole Completion: **Straight Wall**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	-2	3	Cement 1 Bags/Sacks
	3	12	Bentonite 4 Bags/Sacks

Seal Method: **Poured**

Distance to Property Line (ft.): **50+**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **29 ft. below land surface on 2021-09-23**

Measurement Method: **Steel Tape**

Packers: **Rubber at 1 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted**

Yield: 20 GPM

	Strata Depth (ft.)	Water Type
Water Quality:	32 - 40	No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill** License Number: **4168**

Comments: **No Data**

Lithology:			Casing:					
DESCRIPTION & COLOR OF FORMATION MATERIAL			BLANK PIPE & WELL SCREEN DATA					
Top (ft.)	Bottom (ft.)	Description	Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	1	Topsoil	4.5	Blank	New Plastic (PVC)	40	-2	105
1	30	Red Sandy Clay	4.5	Perforated or Slotted	New Plastic (PVC)	40 0.020	105	125
30	125	Red Granite						

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540