

## STATE OF TEXAS WELL REPORT for Tracking #104418

Owner:	Vista Encantata	Owner Well #:	No Data
Address:	5925 Forest Lane, Ste. 505 Dallas, TX 75230	Grid #:	57-27-4
Well Location:	Vista Encantata, Lot V TX	Latitude:	30° 34' 34" N
Well County:	Llano	Longitude:	098° 43' 28" W
		Elevation:	No Data
Type of Work: <b>New Well</b>		Proposed Use: <b>Domestic</b>	

Drilling Start Date: **2/14/2007**      Drilling End Date: **2/14/2007**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	<b>6.75</b>	<b>39</b>	<b>40</b>
	<b>6</b>	<b>0</b>	<b>39</b>
	<b>6</b>	<b>40</b>	<b>80</b>

Drilling Method: **Air Hammer**

Borehole Completion: **Filter Packed**

	Top Depth (ft.)	Bottom Depth (ft.)	Filter Material	Size
Filter Pack Intervals:	<b>25</b>	<b>39</b>	<b>Gravel</b>	<b>4A</b>

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	<b>0</b>	<b>3</b>	<b>1 Cement</b>
	<b>3</b>	<b>25</b>	<b>4 Bentonite</b>

Seal Method: **Grout**

Distance to Property Line (ft.): **No Data**

Sealed By: **Driller**

Distance to Septic Field or other  
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Water Level: **34 ft. below land surface on 2007-02-14**      Measurement Method: **Unknown**

Packers: **No Data**

Type of Pump: **Submersible**      Pump Depth (ft.): **60**

Well Tests: **Jetted**      **Yield: 45 GPM**

Water Quality:	Strata Depth (ft.)	Water Type
	35-39, 45	good (360 ppmTDS)

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

**Certification Data:** The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

**Company Information:** **Virdell Drilling Inc.**  
**111 E. Grayson St.**  
**Llano, TX 78643**

**Driller Name:** **Taylor Virdell Jr.** **License Number:** **1900**

**Apprentice Name:** **James Caleb Virdell** **Apprentice Number:** **3254**

**Comments:** **No Data**

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL			Casing: BLANK PIPE & WELL SCREEN DATA			
Top (ft.)	Bottom (ft.)	Description	Dia. (in.)	New/Used	Type	Setting From/To (ft.)
0	2	Topsoil	6"	N	PVC +2	- 30 sch 40
2	25	Gravel & Clay	6"	N	PVC, Custom Slott	30 - 40 sch 40
25	39	Broken Red & Black Metamorphic				
39	80	Red & Black Metamorphic				

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 334-5540**