#### STATE OF TEXAS WELL REPORT for Tracking #187651

Owner:

**Bubba Beckham** 

Owner Well #:

No Data

Address:

P.O. Box 280

Llano, TX 78643

Grid #:

57-20-5

Well Location:

Latitude:

30° 42' 01" N

.5 mi. S of Lottie Roberts Curve on Hwy. 71; .3 mi. E behind house

Longitude:

098° 33' 57" W

Llano

Elevation:

No Data

Type of Work: New Well

Well County:

Proposed Use:

**Domestic** 

Drilling Start Date: 7/23/2009

Drilling End Date: 7/23/2009

Borehole:

Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
9	0	30
6.75	30	31
30 to 4000 due from the control of t	31	100

Drilling Method:

Air Hammer

Borehole Completion:

**Open Hole** 

Annular Seal Data:

Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
1	3	1 Cement
3	30	5 Bentonite

Seal Method: Grout

Distance to Property Line (ft.): No Data

Sealed By: Driller

Distance to Septic Field or other concentrated contamination (ft.): No Data

Distance to Septic Tank (ft.): No Data

Method of Verification: No Data

Surface Completion:

**Pitless Adapter Used** 

Water Level:

31 ft. below land surface on 2009-07-23

Measurement Method: Unknown

Packers:

No Data

Type of Pump:

Submersible

Pump Depth (ft.): 80

Well Tests:

**Jetted** 

Yield: 45 GPM

Water Type
Water Quality: 35 good (430 ppmTDS)

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained injurious constituents?:

No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information:

Virdell Drilling Inc.

111 E. Grayson St. Llano, TX 78643

Driller Name:

Taylor Virdell Jr.

License Number:

1900

Apprentice Name:

James Caleb Virdell

Apprentice Number:

57668

Comments:

No Data

### Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

## Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	1	Topsoil
1	15	Brown Clay & Gravel
15	31	Weathered Red Metamorphic
31	75	Red & Black Metamorphic
75	100	Pink Metamorphic

# Dia. (in.) New/Used Type Setting From/To (ft.) 6" N PVC +2 - 31 sch 40

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540

# STATE OF TEXAS WELL REPORT for Tracking #13811

Owner:

**Robert Beckham** 

No Data Owner Well #:

Address:

P.O. Box 280

Grid #:

57-20-5

Llano, TX 78643

mi. N/E in pasture

Latitude:

30° 42' 00" N

Well Location:

.6 mi. S/E from CR 306 on Hwy. 71; .3

Longitude:

098° 33' 58" W

TX

Well County:

Llano

Elevation:

No Data

Type of Work:

**New Well** 

Proposed Use:

**Domestic** 

Drilling Start Date: 10/31/2002

Drilling End Date: 10/31/2002

Borehole:

Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)	
- и поставления в поставления		22	
6.75	22	23	
	23	200	

Drilling Method:

Air Hammer

Borehole Completion:

**Open Hole** 

Annular Seal Data:

Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
	23	4

Seal Method: Grout

Distance to Property Line (ft.): No Data

Sealed By: Driller

Distance to Septic Field or other

concentrated contamination (ft.): No Data

Distance to Septic Tank (ft.): No Data

Method of Verification: No Data

Surface Completion:

Pitless Adapter Used

Water Level:

30 ft. below land surface on 2002-10-31

Measurement Method: Unknown

Packers:

No Data

Type of Pump:

Submersible

Pump Depth (ft.): 180

Well Tests:

**Jetted** 

Yield: 10 GPM

Water Quality:

Strata Depth (ft.)	Water Type	
40 - 41	good (440 ppmTDS)	

Chemical Analysis Made:

Did the driller knowingly penetrate any strata which

contained injurious constituents?: No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information:

Virdell Drilling Inc.

111 E. Grayson St. Llano, TX 78643

Driller Name:

Lynn Hoy

License Number:

4071

Comments:

No Data

#### Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

#### Casing: BLANK PIPE & WELL SCREEN DATA

No

Top (ft.)	Bottom (ft.)	Description
0	2	Topsoil
2	19	Metamorphic Gravel
19	40	Red Metamorphic
40	55	Gray & Red Metamorphic
55	72	Black & Red Metamorphic
72	100	Red Metamorphic
100	115	Black Metamorphic
115	150	Red Metamorphic
150	200	Red & Black Metamorphic

Dia. (in.)	New/Used	Type	Setting From/To (ft.)
6" N P\	/C +2 - 23	sch 40	

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540