STATE OF TEXAS WELL REPORT for Tracking #339747				
Owner:	Guy Riley	Owner Well #:	2	
Address:	PO Box 4384 Horseshoe Bay, TX 78657	Grid #:	57-10-9	
Well Location:	4690 State Hwy 71 West	Latitude:	30° 47' 10" N	
	Llano, TX 78643	Longitude:	098° 45' 07" W	
Well County:	Llano	Elevation:	1149 ft. above sea level	
Type of Work:	New Well	Proposed Use:	Stock	

Drilling Start Date: 8/25/2013 Drilling End Date: 8/25/2013

	Diamatar (in	Top Dor	14 /ft)	Pottom Donth (ft.)		
Borehole:	Diameter (in.,		<i>uri (it.)</i>	Bottom Depth (ft.)		
Dorenole.	9	0		10		
	6.75	10		200		
Drilling Method:	Air Hammer; Air	Rotary				
Borehole Completion:	Straight Wall					
	Top Depth (ft.)	Bottom Depth (ft.)	De	scription (number of sacks & material)		
Annular Seal Data:	-2	10		3		
Seal Method: po	oured slurry	Dis	tance to P	roperty Line (ft.): 200+		
Sealed By: Driller		Distance to Septic Field or other concentrated contamination (ft.): 500+				
		D	istance to	Septic Tank (ft.): No Data		
			Metho	d of Verification: owner		
Surface Completion:	Surface Sleeve Ir	nstalled				
Water Level:	50 ft. below land	surface on 2013-08-2	5 Meas	surement Method: Unknown		
Packers:	rubber 10'					
Type of Pump:	No Data					
Well Tests:	Jetted	Yield: 8 GPM wit	h 0 ft. dra	wdown after .5 hours		

	Strata Depth (ft.)	Water Type		
Water Quality:	45, 150	No Data		
		Chemical Analysis Made	: No	
	Did the driller k	nowingly penetrate any strata which contained injurious constituents?		
Certification Data:	driller's direct supervis correct. The driller un	at the driller drilled this well (or the w sion) and that each and all of the sta nderstood that failure to complete the surned for completion and resubmitta	tements he e required it	rein are true and
Certification Data: Company Information	driller's direct supervis correct. The driller un the report(s) being ret	sion) and that each and all of the stand inderstood that failure to complete the surned for completion and resubmitta	tements he e required it	rein are true and
	driller's direct supervis correct. The driller un the report(s) being ret	sion) and that each and all of the stand inderstood that failure to complete the surned for completion and resubmitta	tements he e required it	rein are true and
	driller's direct supervis correct. The driller un the report(s) being ret Walden Drilling Inc 1690 cr 102	sion) and that each and all of the stand inderstood that failure to complete the curned for completion and resubmitta	tements he e required it	rein are true and

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description	Dia
0	2	topsoil	4.5
2	46	sandstone sand clay gravel	4.5
46	200	red and grey granite	

Casing:				
BLANK PIPE & WELL SCREEN DATA				

. ,	New/Used		Setting From/To (ft.)
15 incl	n now edr	17 nvc	+2 to 110 blank

4.5 inch new sdr 17 pvc 110 to 200 slotted .125

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540